


ASSEMBLY INSTRUCTIONS VANITY STOOT








NOTE: ASSEMBLE UNIT ON A SOFT SURFACE. ASSEMBLEZ L'UNITÉ SUR UNE SURFACE MOLLE.

DO NOT TIGHTEN BOLTS UNTIL THE UNIT IS COMPLETELY ASSEMBLED. NE SERREZ PAS LES BOULONS JUSQU' À CE QUE L'UNITÉ SOIT COMPLÈTEMENT ASSEMBLÉE

LIST OF PARTS AND HARDWARE:								
No.	Description			Q'ty				
В	0	Flat washer	Φ1/4"*16*1.5mm	8				
С	0	Lock washer	Φ1/4"	8				
D	Mar Nag	Bolt	Φ1/4"*50mm	8				
Е	(Allen wrench	4mm	1				
1		Cushion		1				
2		Legs		4				

BOB'S FURNITURE ASSEMBLY INSTRUCTIONS

VANITY MIRROR



LIST OF PARTS AND HARDWARE(VANITY MIRROR)							
No.		Description					
Н	0	Flat washer	Φ1/4"*16*1.5mm	12			
I	Ø	Lock washer	Φ1/4"	12			
K	en line	Bolt	Φ1/4"*40mm	12			
Е		Allen wrench	4mm	1			
3	T.	Vanity Mirror		1			
4		Support		2			


NOTE:
ASSEMBLE UNIT ON A SOFT SURFACE.
ASSEMBLEZ L'UNITÉ SUR UNE SURFACE MOLLE.

LIST OF PARTS AND HARDWARE(VANITY L&R)						
No.		Description				
Α	D	Furniture tipping restraint		2		
В	0	Flat washer	Φ5/16"*19*1.5mm	16		
C	Ø	Lock washer	Φ5/16"	16		
D	THE RED	Bolt	Φ5/16"*50mm	16		
E	~	Allen wrench	4mm	1		
F	\$	Glass shelf support		4		
G	•	Bolt	Φ1/4"*15mm	4		
Н	$\langle \cdot \rangle$	Glass shelf		1		
1		Vanity L&R		1 Set		
2	4	Legs		8		

BOB'S FURNITURE

ASSEMBLY INSTRUCTIONS

VANITY VANITY MIRROR





MARNING: To avoid serious personal injury:

- · Carefully and strictly follow assembly instructions. Improper assembly of furniture can result in structural failure, instability of the product, or tip-over.
- · Monitor and carefully control the assembly components. These include small parts and hardware that may present a choking hazard to small children. Bob's furniture should be assembled only by responsible adults and children should not be involved in the assembly process.
- · Where provided, wall mounting hardware should always be used as prescribed in these instructions to anchor furniture to wall. Proper use of the wall mounting hardware can significantly reduce the potential for furniture tip-over and crushing injuries.