

ASSEMBLY INSTRUCTIONS FOR DRESSER

Cautions: Please read instructions thoroughly before unpacking assembly parts. Sharp, exposed staple tips can cause injury, therefore, for your protection, please remove any exposed staples used in parking.

1. We recommend that you should assemble this product with the assistance of another person; this will make assembly easier, and will help to eliminate damage to the product or injury to persons during assembly.
2. Be sure to check all packing materials carefully for small parts that may have come loose inside the carton during shipment.
3. Please do not over tighten screws or bolts.
4. Please put all parts on a non-abrasive floor before assembly, and follow the assembly steps to assemble your newly purchased product correctly and efficiently.


PART LIST

No.	Part Description	Code.	Q'ty
A	Dresser		1
B	Legs	PCT800CGLEG	4
C	Center Support Leg With Leveler	PCT800DRSPL	1


HARDWARE LIST

No.	Hardware Description	Code.	Q'ty
1	 Tipping Restraint	ATKT	1SET


Remark : Please be noted that the safety bracket set with instruction is attached at the right first drawer.



Tipping Restraint



Step 2



The legs inside the bottom drawer

Step 1



WARNING

CLIMBING MAY RESULT IN SERIOUS INJURY	SUBIRSE PUEDE CAUSAR LESIONES GRAVES	MONTER SUR LE MEUBLE OU UNE PARTIE DU MEUBLE PEUT CAUSER DES BLESSURES GRAVES
CHILD SAFETY <i>Anchor it and protect a child. Use of anti-tip kit is required.</i>	SEGURIDAD DE LOS NIÑOS <i>Fijelo y proteja a un niño Es necesario. uso de un sistema antivuelco.</i>	SÉCURITÉ DE L'ENFANT <i>Ancrez-le et protégez les enfants. Utilisez toujours un système antibasculement.</i>
Anti-tip kit Located here	El sistema antivuelco está ubicado aquí	Le système antibasculement est situé ici
		
Anti-tipping restraint hardware kit is attached to back of furniture.	El sistema de accesorios de sujeción antivuelco se encuentra en la parte de atrás del mueble.	Le système de retenue antibasculement est attaché à l'arrière du meuble.
Place heaviest items in the lower drawers.	Coloque los objetos más pesados en los cajones inferiores.	Placez les éléments plus lourds dans les tiroirs inférieurs.
Unless specifically designed to accommodate, do not set TVs or other heavy objects on top of this product.	A menos que esté diseñado específicamente para ello, no coloque televisores u otros objetos pesados sobre este producto.	Sauf si la conception le permet, ne placez pas de téléviseur ni d'objets lourds sur ce produit.
Never allow children to climb or hang on drawers, doors, or shelves.	Nunca permita que los niños se suban o se cuelguen de cajones, puertas o estantes.	Ne permettez jamais à des enfants de monter dans les tiroirs, sur les portes ou sur les étagères, ou de s'y pendre.
Never open more than one drawer at a time.	Nunca abra más de un cajón a la vez.	N'ouvrez jamais plus d'un tiroir à la fois.
Do not remove the drawer interlock system.	No desactive ni retire el sistema de bloqueo de los cajones.	Ne défaites ni ne retirez jamais le système de verrouillage des tiroirs.
Use of tip-over restraints may only reduce, but not eliminate, the risk of tip-over.	El uso de las sujeciones antivuelco sólo puede reducir, y no eliminar, el riesgo de vuelco.	L'utilisation d'un système antibasculement peut réduire le risque de basculement, mais ne l'élimine pas.

 WARNING: To avoid serious personal injury:

- Carefully and strictly follow assembly instructions. Improper assembly of furniture can result in structural failure, instability of the product, or tip-over.
- Monitor and carefully control the assembly components. These include small parts and hardware that may present a choking hazard to small children. Bob's furniture should be assembled only by responsible adults and children should not be involved in the assembly process.
- Where provided, wall mounting hardware should always be used as prescribed in these instructions to anchor furniture to wall. Proper use of the wall mounting hardware can significantly reduce the potential for furniture tip-over and crushing injuries.